


Patrol Power 2013-Up Ford Interceptor/Taurus W/O Trunk Vault
Fuse Panel Mounting Location Part # PAN030313



In order to complete installation of fuse panel, inner trunk liner panel must be removed from vehicle



View of mounting location with trunk liner panel removed.



View of panel installed and battery cable not yet connected to factory power buss.

Patrol Power 2013-Up Ford Interceptor/Taurus W/O Trunk Vault
Fuse Panel Mounting Location Part # PAN030313



Factory trunk liner panel must be cut to provide access to fuse panel. To define borders of cut out area, replace panel and feel for fuse panel behind the trunk liner panel by hand, then mark the corners with a permanent marker. Panel can be cut by carefully using razer knife or heavy duty scissors



Detail of cut to provide access to circuit breaker. Note "trap door" that is created for circuit breaker.



Completed installation.